1. Built-in MPI with 187.5K baud rate function is only available on the <u>MT8100iv2</u> and <u>MT8070iH2</u> which have a "MPI 187.5K" label on the rear cover as shown in the picture below:




- 2. EB8000 must be V3.1.0, and select SIEMENS S7/300 MPI driver for S7-300 and S7-200 PLC, or select SIEMENS S7/200 driver and set the baud rate to 187.5K.
- 3. One HMI is able to connect to one 187.5K device only.
- 4. It doesn't support to use Extended Address mode or change HMI station no.. And the HMI station no. has to be 0 when S7-300 MPI driver is in use.

Please refer to below for connection diagram:



Weintek Labs., Inc.

3F, 910 Chung Cheng Rd, Chung Ho, Taipei Hsien, 235 Taiwan Tel : +886-2-22286770 Fax: +886-2-22286771 Email: <u>servicemail@weintek.com</u>





Weintek Labs., Inc.

3F, 910 Chung Cheng Rd, Chung Ho, Taipei Hsien, 235 Taiwan Tel : +886-2-22286770 Fax: +886-2-22286771 Email: <u>servicemail@weintek.com</u>